



Karl Pedross AG • 1-39021 Latsch (BZ) • Industriezone 1C Tel. +39 0473 722 200 • Fax +39 0473 722 300 • info@pedross.com • www.pedross.com

Care Instructions for Skirtings

Cleaning and Maintenance

Use a slightly damp cloth to wipe your skirtings clean; do not use a wet cloth. Caution! Avoid getting the skirtings wet when cleaning the floor.

Do not use abrasives, foaming cleansers or any products containing ammonia.

Color change

Changes in color and wood grain are natural and are a testament to the authenticity of the wood as a natural product. Expose the wood, foil or paper surface, to as steady a light as possible. Wood changes its color over the years depending on the intensity of UV radiation.

Moisture

Wood is a piece of living nature. Wood and MDF should not be exposed to moisture or ever become wet, because they absorb water, which may lead to changes in the shape or graying. Major alterations can be prevented by a healthy indoor climate. We recommend a room temperature of $18-20\,^{\circ}$ C and relative humidity of 55-70%.

Storage

Skirtings are properly stored standing or lying down on a flat surface. The skirtings should be protected from direct sunlight and moisture. The ideal storage climate is a steady temperature of about 18 C° and a humidity of 55-70%.

The cleaning instructions are based on practical experience. We do not assume any liability for completeness, accuracy and applicability.

Your Pedross Team